

# RECALL NOTICE

REI Announces Recall of  
2015 evrgrn Campfire Rocker



LOOK FOR THE SMALL  
DIVOT ON THE LEFT  
REAR FASTENERING  
HARDWARE



NO DIVOT: RECALLED



DIVOT: NOT AFFECTED



Hazard: The rocking chair may overbalance backwards posing a fall risk to the user.

Recalled Product: First generation evrgrn Campfire Rockers sold between April and August of 2015 without a divot on the left rear fastening hardware.

Remedy: Consumers should stop using the chairs immediately and contact REI for a replacement or refund.

For more information:

**1-800-426-4840**

4am to 11pm PT

[www.rei.com](http://www.rei.com)

This recall is being conducted in cooperation with the U.S. Consumer Product Safety Commission.

Post Until 3/1/2016